


**SKODA Rapid: 1GRL145**

Vinnnumber:	<b>TMBEJ6NH0E4531557</b>	Versionname:	<b>RAPID SB Ambition 90PK</b>
First Registrationdate:	<b>9/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>178968</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4112</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/45/16/86 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Dunlop: 2,5 mm</b>	Re.R.	<b>Dunlop: 2,5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	513,80
-------------------	--------

Bonnet, Bump(s) and scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Interior, Dirty, Acceptable	0,00
-----------------------------	------

*No pictures to display*

Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Internal Boot Lining L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Roof, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Internal Boot Lining R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Certificate Of Conformity, Missing, E - Replace	150,00



Engine protective plate, Missing, E - Replace	65,00
---	-------



Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Wing R L, Bump(s) and scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Boot cover, Missing, E - Replace	50,00
----------------------------------	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Roof, Stone chip(s), Acceptable	0,00
---------------------------------	------

*No pictures to display*