




VOLVO V40: 1FCI227			
Vinnnumber:	YV1MV8481D2059765	Versionname:	V40 D2 Base 115PK
First Registrationdate:	23/05/2013	Fiscalpower:	
Expertise Mileage:	129477	Power Kw:	84
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2709
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment	
Repair kit	No Compressor Yes
Total cost ex VAT	611,65
Boot cover, Stain, Cleaning	25,00



Seat cover R L, Stain, Cleaning	25,00
---------------------------------	--------------



Roof, Scratch(es), Acceptable 0,00



Seat cover F L, Stain, Acceptable 0,00



Door F R, Bump(s), Acceptable 0,00



Alloy rim F L, Scratch(es), Acceptable 0,00



Tyre repair kit, Incomplete, E - Replace 210,53



Rearview mirror housing R, Difference in color, LI - Repair and paint (complete) 115,56



Door R L, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Bumper R, Bump(s) and scratch(es), Acceptable 0,00



Wing R L, Repaired, Acceptable 0,00

No pictures to display

Door F L, Bump(s) and scratch(es), Acceptable 0,00




Wing R L, Scratch(es), Acceptable 0,00



Ceiling, Stain, Cleaning 25,00



Rearview mirror housing L, Difference in color, LI - Repair and paint (complete) 115,56



Front bumper, Scratch(es), Acceptable 0,00

