


BMW X3: 1GBF961

Vinnnumber:	WBAWY110X00C57903	Versionname:	X3 sDrive18 136PK
First Registrationdate:	13/12/2013	Fiscalpower:	
Expertise Mileage:	80934	Power Kw:	100
Bodytype:	SUV	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3406
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/17/99 H LightMetal			
Winter tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2763,50
Wing R R, Bump(s), Acceptable	0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------






Wing R L, Scratch(es), It - Spot repair 115,56



Roof, Chemical pollution, LI - Repair and paint (complete) 577,80



Bumper R, Scratch(es), Smart repair 110,64



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Protection plate M, Tear, E - Replace 74,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Wing R R, Scratch(es), It - Spot repair 115,56



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door F L, Scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display