



BMW 3: 1FHY789

Vinnumber:	WBA3K31070F746785	Versionname:	3 TOURING 320d 163PK
First Registrationdate:	3/07/2013	Fiscalpower:	
Expertise Mileage:	170591	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4322
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/6/16/92 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------








Total cost ex VAT 759,34

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F L, Scratch(es), Acceptable

0,00

<i>No pictures to display</i>		
Backrest cover F L, Damaged, Acceptable		0,00
		
Wing F R, Scratch(es), LI - Repair and paint (complete)		220,18
		
Wing R L, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)		211,80
		
Roof pillar L, Scratch(es), It - Spot repair		115,56
