




MINI Mini: 1ERL633			
Vinnnumber:	WMWSW71010T331650	Versionname:	MINI Cooper SD 136PK DPF
First Registrationdate:	1/03/2013	Fiscalpower:	
Expertise Mileage:	85874	Power Kw:	100
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4314
Number of doors	3		
Number of seats	4		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/45/17/84 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2108,05
Wing R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), LI - Repair and paint (complete)			318,35





Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00




Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Wing R L, Scratch(es), It - Spot repair 115,56



Interior, Dirty, Cleaning 0,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Stain, Cleaning 50,00



Wing F R, Scratch(es), It - Spot repair 115,56



Alloy rim F L, Damaged, E - Replace 235,20



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Chemical polution, LI - Repair and paint (complete) 100,00

