



VOLKSWAGEN Amarok: 1EZG364

Vinnnumber:	WV1ZZZ2HZDH015295	Versionname:	AMAROK 2C 4M Trendline
First Registrationdate:	26/04/2013	Fiscalpower:	140PK
Expertise Mileage:	155640	Power Kw:	103
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1229
Maintenance:	+ 32500 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/70/16/107 T LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1039,99
-------------------	----------------

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	362,02
---	---------------





Bodywork, Not original part, Remove lettering 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00



Interior, Damaged, Acceptable 0,00

No pictures to display

Door F L, Bump(s), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Armrest R M, Damaged, Smart repair 64,32




Ignition key, Missing, E - Replace 150,00

No pictures to display


Windscreen, Repaired, Acceptable 0,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 348,09



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display