



**PEUGEOT 3008: ZH4564**

Vinnumber:	<b>VF30UBHXMFS126711</b>	Versionname:	<b>1.6 HDI 84KW BUSINESS LINE</b>
First Registrationdate:	<b>25/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>101808</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4121</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/98 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	1147,80
-------------------	---------

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Bumper R, Damaged, LI - Repair and paint (complete)

211,80



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Bump(s), Acceptable

0,00

*No pictures to display*

Door frame R R, Bump(s) and scratch(es), It - Spot repair

115,56



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56

