


**MERCEDES A: 1FGP263**

Vinnumber:	<b>WDD1760121J120778</b>	Versionname:	<b>A 180 CDI BE 109PK</b>
First Registrationdate:	<b>24/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>77857</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4716</b>
Maintenance:	<b>A DANS 52 J</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Yokohama: 6 mm</b>	Fr.R.	<b>Yokohama: 6 mm</b>
	Re.L.	<b>Yokohama: 7 mm</b>	Re.R.	<b>Yokohama: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>740,18</b>
-------------------	---------------

Alloy rim F L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Instruction book, Missing, E - Replace	<b>0,00</b>
--	-------------

*No pictures to display*

Wing F L, Bad repair, LI - Repair and paint (complete)	<b>220,18</b>
--	---------------



Wing R R, Bad repair, LI - Repair and paint (complete)	<b>308,20</b>
--	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Maintenance book, Missing, E - Replace	0,00
--	------

*No pictures to display*

Bumper R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*