



VOLVO V40: 1ESH236

Vinnnumber:	YV1MV8481D2045610	Versionname:	V40 D2 Base 115PK
First Registrationdate:	7/03/2013	Fiscalpower:	
Expertise Mileage:	159448	Power Kw:	84
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1206
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 V LightMetal				
Summer tyres:	Fr.L.	Fulda: 3 mm	Fr.R.	Fulda: 3 mm
	Re.L.	Fulda: 4 mm	Re.R.	Fulda: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2215,74
-------------------	---------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof pillar R, Bad repair, Acceptable	0,00
---------------------------------------	------



Door panel F L, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Rear spoiler, Chemical polution, LI - Repair and paint (complete)

115,56



Wheel cover F R, Scratch(es), E - Replace

30,00



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Wing F L, Bump(s), LI - Repair and paint (complete)

220,18



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80

