



**BMW 5: 132CCR**

Vinnumber:	<b>WBAMX51060C760406</b>	Versionname:	<b>5 TOURING 530d 245PK</b>
First Registrationdate:	<b>18/10/2010</b>	Fiscalpower:	
Expertise Mileage:	<b>113777</b>	Power Kw:	<b>180</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1708</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Seats electric F L
Windows electric F	Sun Roof electric
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunction	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>245/45/18/100 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Total cost ex VAT	1500,89
Sill outer R, Scratch(es), LI - Repair and paint (complete)	372,60




Roof, Chemical polution, Acceptable	0,00
-------------------------------------	------

No pictures to display


Bonnet, Chemical polution, LI - Repair and paint (complete)	348,00
---	--------

Bumper, Chemical solution, LI - Repair and paint (complete)		340,00
		
Interior, Dirty, Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Tyre F L, Damaged, E - Replace		153,60

		
Alloy rim F R, Scratch(es), E - Replace		277,44

		
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)		254,16

		
Wing F R, Repaired, Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00

		
--	--	--