




FORD KUGA: 1LDN529			
Vinnnumber:	<b>WFOAXXWPMFY82176</b>	Versionname:	<b>2.0 TDCI 2WD 88KW TREND</b>
First Registrationdate:	<b>28/08/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>115153</b>	Power Kw:	<b>88</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1606</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>235/55/17/99 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

Assistance equipment	
Emergency spare wheel	<b>Yes</b>
Compressor	<b>Yes</b>
Total cost ex VAT	<b>2287,66</b>
Door F L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bumper corner R R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>369,84</b>



Roof, Chemical pollution, LI - Repair and paint (complete)	<b>0,00</b>
--	-------------



Wing F L, Scratch(es), It - Spot repair 115,56



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R L, Chemical polution, LI - Repair and paint (complete) 369,84



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Chemical polution, LI - Repair and paint (complete) 264,22



Bumper corner R L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Chemical polution, LI - Repair and paint (complete)

382,02



Door R R, Scratch(es), Acceptable

0,00

No pictures to display