



OPEL Insignia: 1EKU185

Vinnumber:	W0LGM8EL5D1028606	Versionname:	INSIGNIA BRE ecoFL.Edit.150ys DPF 130PK
First Registrationdate:	9/01/2013	Fiscalpower:	96
Expertise Mileage:	106666	Power Kw:	96
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4101
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	NOT OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 W Steel			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


















Total cost ex VAT 1795,85

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18

			
Wheel cover F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wheel cover F R, Damaged, E - Replace			30,00
			
			
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)			318,35
			
Roof pillar L, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Tailgate, Scratch(es), LI - Repair and paint (complete)			301,68
			
Wheel cover R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door frame R L, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)			115,56
			
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)			308,20
			
Bonnet, Chemical polution, LI - Repair and paint (complete)			290,08
