




VOLKSWAGEN Crafter 35MWB: 1HKA429			
Vinnnumber:	WV1ZZZ2ZF6007822	Versionname:	CRAFTER 35 B/F2C MWB
First Registrationdate:	6/08/2014	Fiscalpower:	109PK
Expertise Mileage:	192292	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	TRU13
Number of doors:	6		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F			
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/65/16/115 R Steel			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			749,16
Bodywork, Not original part, Acceptable			0,00



Front bumper, Bump(s) and scratch(es), Smart repair	110,64
---	---------------



Interior, Damaged, Acceptable 0,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), It - Spot repair 115,56



Interior, Damaged, Acceptable 0,00





Bumper grille, Scratch(es), E - Replace 30,30



Door trim F R, Scratch(es), Acceptable 0,00

No pictures to display

Sliding door R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Bumper cover R M, Scratch(es), Acceptable 0,00

No pictures to display

Covering mid pillar L, Scratch(es), Smart repair 110,64

