



RENAULT Grand Scenic: 1FJG087

Vinnumber:	VF1JZ14M649109096	Versionname:	GRAND SCENIC Bose Ed.5pl.110PK
First Registrationdate:	15/07/2013	Fiscalpower:	
Expertise Mileage:	146949	Power Kw:	81
Bodytype:	Hatchback	Body color:	Burgundy
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2432
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2909,04
-------------------	---------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Rocker panel inner R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Bump(s), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim R L, Rust, LI - Repair and paint (complete) 95,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35




Rocker panel inner F L, Scratch(es), LI - Repair and paint (complete) 115,56






Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08





Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

318,35




Seat cover F L, Worn, Acceptable

0,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

308,20



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

318,35



