



## CITROEN C4 Picasso: 1ANV743

Vinnnumber:	<b>VF7UA9HR8BJ532245</b>	Versionname:	<b>GR.C4 PICASSO 7pl.Business GPS FAP</b>
First Registrationdate:	<b>17/02/2011</b>	Fiscalpower:	<b>112PK</b>
Expertise Mileage:	<b>142690</b>	Power Kw:	<b>82</b>
Bodytype:	<b>MPV</b>	Body color	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2305</b>
Number of doors	<b>5</b>		
Number of seats	<b>7</b>		
Number head rests	<b>7</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/55/16/93 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Fulda: 5 mm</b>	Fr.R.	<b>Fulda: 5 mm</b>
	Re.L.	<b>Bridgestone: 3 mm</b>	Re.R.	<b>Bridgestone: 3 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	671,24
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper corner R L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), LI - Repair and paint (complete) 301,68



Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Front bumper, Bad repair, Acceptable 0,00



Roof pillar L, Rust, Acceptable 0,00



Bonnet, Deformed, I - Repair 96,00



Door R R, Bump(s), PDR - Knock out without painting 63,00

