


**TOYOTA Yaris: 1HAB054**

Vinnnumber:	<b>VNKKD3D310A091042</b>	Versionname:	<b>YARIS BER Hybrid Style</b>
First Registrationdate:	<b>2/06/2014</b>	Fiscalpower:	<b>74PK Aut.</b>
Expertise Mileage:	<b>77854</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3707</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining artificial leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

195/50/16/84 V LightMetal				
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	1989,84
-------------------	---------

Internal Boot Lining R, Scratch(es), Acceptable	0,00
-------------------------------------------------	------

*No pictures to display*

Door panel R L, Scratch(es), E - Replace	96,00
------------------------------------------	-------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	246,56
---------------------------------------------------------------------	--------



Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s), LI - Repair and paint (complete) 254,68



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 344,40



Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Damaged, Le - Replace and paint 607,20



Luggage space cover, Damaged, E - Replace 60,00



Door R R, Bad repair, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44





Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R L, Scratch(es), LI - Repair and paint (complete)	115,56



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel F L, Scratch(es), E - Replace	96,00

