


**FORD B-Max: 1EJR760**

Vinnumber:	<b>WF0KXXERJKCS27373</b>	Versionname:	<b>B-MAX Trend 75PK</b>
First Registrationdate:	<b>2/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>82242</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3722</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/60/15/88 H Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 7 mm</b>	Re.R.	<b>Bridgestone: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	3061,26
-------------------	---------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

*No pictures to display*

Front bumper, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Bonnet, Scratch(es), LI - Repair and paint (complete)	232,06
---	--------



Tailgate, Accident, Le - Replace and paint 846,92



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68



Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Bumper R, Accident, Le - Replace and paint 535,20



Door F L, Scratch(es), Acceptable 0,00


No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56






Wheel cover R R, Scratch(es), E - Replace

24,00



Bumper grille, Broken, E - Replace

30,72



Wheel cover F R, Damaged, E - Replace

24,00



Ceiling, Strained , E - Replace

424,00

