


TOYOTA Auris: 1GEZ749

Vinnnumber:	SB1ZS3JE20E061175	Versionname:	AURIS TOUR.SP. HSD Comfort CVT 99PK Aut.
First Registrationdate:	21/01/2014	Fiscalpower:	
Expertise Mileage:	50053	Power Kw:	73
Bodytype:	Break	Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4708
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 2,5 mm	Fr.R.	Bridgestone: 2,5 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	164,56
-------------------	--------

Wing R R, Bad repair, Paint	0,00
-----------------------------	------




Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display


Seat cover R, Stain, Cleaning	25,00
-------------------------------	-------



Wing R L, Bad repair, Paint 0,00



Door R R, Bad repair, Paint 0,00



Rear spoiler, Chemical polution, LI - Repair and paint (complete) 139,56



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Deformed, Le - Replace and paint 0,00



Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Bad repair, Paint 0,00

