



**LAND ROVER Evoque: 1EH0986**

Vinnnumber:	<b>SALVA2DC7DH722326</b>	Versionname:	<b>EVOQUE TD4 4WD Pure</b>
First Registrationdate:	<b>5/12/2012</b>	Fiscalpower:	<b>150PK</b>
Expertise Mileage:	<b>143123</b>	Power Kw:	<b>110</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3210</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Type of headlighting <b>Headlighting Xenon</b>	Type of Tow bar <b>No Tow bar</b>
Type of GPS <b>No GPS</b>	
Type of Lining <b>Lining leather and alcantara</b>	
Type of climate control <b>Autom climate control</b>	
Sport seats	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/65/17/106 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Semperit: 8 mm</b>	Fr.R.	<b>Semperit: 8 mm</b>
	Re.L.	<b>Semperit: 7 mm</b>	Re.R.	<b>Semperit: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	226,20
Outer door handle F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Smart repair	110,64





Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 0,00



Wing F L, Scratch(es), It - Spot repair 115,56

