



PEUGEOT 2008: 1GWH576

Vinnnumber:	VF3CU8HR0EY007237	Versionname:	2008 Active 68PK
First Registrationdate:	19/05/2014	Fiscalpower:	
Expertise Mileage:	114022	Power Kw:	50
Bodytype:	SUV	Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2108
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Radio multimedia		
Type of headlighting:	Headlighting Halogen	
Type of GPS:	GPS big screen color	
Type of Lining:	Lining fabrics	
Type of climate control:	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/60/16/89 H Steel			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	585,50
-------------------	---------------


Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------


No pictures to display

Protection plate M, Tear, E - Replace	74,00
---------------------------------------	--------------



Door R R, Bad repair, Acceptable	0,00
----------------------------------	-------------





Bumper corner R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Damaged, E - Replace 30,00



Bonnet, Bad repair, Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door F R, Scratch(es), Acceptable 0,00

No pictures to display