


BMW 5: 1GGL520

Vinnnumber:	WBA5C11080D033819	Versionname:	5 BER 518da 136PK Aut.
First Registrationdate:	3/02/2014	Fiscalpower:	
Expertise Mileage:	156444	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4807
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 W LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1091,86
-------------------	---------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display














Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

			Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Door R L, Scratch(es), LI - Repair and paint (complete)	382,02
				
<i>No pictures to display</i>				
			Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>				
			Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	369,84
				
				
<i>No pictures to display</i>				
			Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				