



VOLKSWAGEN Golf: 1FBP101

Vinnumber:	WVWZZZ1KZDM672930	Versionname:	GOLF BRE Trendline BlueMot.DPF 105PK
First Registrationdate:	16/05/2013	Fiscalpower:	
Expertise Mileage:	91168	Power Kw:	77
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4606
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	2		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1117,26

Bodywork, Not original part, Acceptable 0,00



Headrest R M, Missing, E - Replace 60,00





Headrest R R, Missing, E - Replace 60,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Hole, I - Repair 50,00



Windscreen, Stone chip(s), E - Replace 487,20



Interior, Not original part, Acceptable 0,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Headrest R L, Missing, E - Replace 60,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Sill outer R, Bump(s) and scratch(es), It - Spot repair 115,56

