



<b>FORD Fiesta: 1FTN064</b>			
Vinnnumber:	<b>WF0DXXGAKDDC65737</b>	Versionname:	<b>FIESTA BER Titanium ECONetic S/S 95PK</b>
First Registrationdate:	<b>21/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>138820</b>	Power Kw:	<b>70</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3111</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Luggage cover
Radio multimedia	Rear parking sensors
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>175/65/14/82 T LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

<b>Assistance equipment</b>			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	<b>981,44</b>
Wing R R, Scratch(es), Acceptable	<b>0,00</b>

*No pictures to display*

Wing R L, Scratch(es), LI - Repair and paint (complete)	<b>246,56</b>
---	---------------



Door R R, Scratch(es), LI - Repair and paint (complete)	<b>254,68</b>
---	---------------





Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Roof, Chemical polution, LI - Repair and paint (complete) 385,20



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Wing F L, Scratch(es), Acceptable 0,00

*No pictures to display*