



BMW 318d: 1HLC601

Vinnumber:	WBA3D11000P700000	Versionname:	BER 136PK 2014
First Registrationdate:	18/08/2014	Fiscalpower:	
Expertise Mileage:	148512	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4728
Maintenance:	60.000 KM		
Maintenance:	1/05/2022		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Seats electric F L
GPS storage	HD	Seats electric F R
Windows electric F		Central consol F
Windows electric R		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

	Runflat	Yes
--	---------	------------

Total cost ex VAT	1978,17
-------------------	----------------

Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Roof, Dent(s), Acceptable	0,00
---------------------------	-------------

No pictures to display

Sill trim R, Dent(s) and scratch(es), It - Spot repair	163,56
--	---------------



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Stain, Cleaning 25,00



Shutter / cover, Damaged, E - Replace 95,20



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Foglight R, Broken, E - Replace 138,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Roof pillar L, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 404,20



Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), It - Spot repair 115,56




Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace

0,00



Seat cover F R, Stain, Cleaning

25,00

