



|                                    |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| <b>BMW 3 TOURING: 1KPT481</b>      |                          |              |                                 |
| Vinnnumber:                        | <b>WBA3K11050F839826</b> | Versionname: | <b>2.0 318D (100KW) TOURING</b> |
| First Registrationdate:            | <b>11/06/2015</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>132287</b>            | Power Kw:    | <b>100</b>                      |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Light Grey</b>               |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4301</b>                     |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Aluminium</b>         |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

|                                |                              |                      |                      |
|--------------------------------|------------------------------|----------------------|----------------------|
| <b>Options</b>                 |                              |                      |                      |
| Radio CD                       |                              | Central consol F     |                      |
| Windows electric F             |                              | Luggage cover        |                      |
| Windows electric R             |                              | Rear parking sensors |                      |
| Cruise Control                 |                              | Type of Tow bar      | <b>Tow bar fixed</b> |
| Steering wheel multifunctional |                              |                      |                      |
| Radio multimedia               |                              |                      |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                      |
| Type of Lining                 | <b>Lining leather</b>        |                      |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |                      |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                                  |                          |       |                          |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| <b>Degree of wear</b> |                                  |                          |       |                          |
|                       | <b>225/50/17/98 W LightMetal</b> |                          |       |                          |
| Summer tyres:         | Fr.L.                            | <b>Kleber: 7 mm</b>      | Fr.R. | <b>Kleber: 7 mm</b>      |
|                       | Re.L.                            | <b>Continental: 8 mm</b> | Re.R. | <b>Continental: 8 mm</b> |

|  |            |            |               |
|--|------------|------------|---------------|
| <b>Assistance equipment</b>                                    |            |            |               |
| Repair kit   | <b>Yes</b> | Compressor | <b>Yes</b>    |
| <b>Total cost ex VAT</b>                                       |            |            | <b>505,98</b> |
| <b>Bumper R, Scratch(es), LI - Repair and paint (complete)</b> |            |            | <b>211,80</b> |



|  |              |
|--|--------------|
| <b>Protection plate M, Tear, E - Replace</b> | <b>74,00</b> |
|--|--------------|



|   |        |
|---|--------|
| Roof, Dent(s), Acceptable                               | 0,00   |
| <i>No pictures to display</i>                           |        |
| Front bumper, Scratch(es), Acceptable                   | 0,00   |
| <i>No pictures to display</i>                           |        |
| Wing F R, Scratch(es), LI - Repair and paint (complete) | 220,18 |

