


PEUGEOT Partner: 1GWA266

Vinnnumber:	VF37A9HF0EN517336	Versionname:	PARTNER B/F L1H1 Conf.120 90PK
First Registrationdate:	15/05/2014	Fiscalpower:	
Expertise Mileage:	165225	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2302
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1396,19
-------------------	---------

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Roof pillar L, Dent(s) and scratch(es), LI - Repair and paint (complete)	261,14
--	--------



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	386,02
---	--------



Wheel aperture R L, Scratch(es), Acceptable 0,00

No pictures to display

Engine protective plate, Tear, E - Replace 69,00



Rear floor , Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Wheel aperture R R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Dent(s), LI - Repair and paint (complete) 376,88



Wing R R, Dent(s), LI - Repair and paint (complete) 303,15



Window F R door, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror R complete, Scratch(es), Acceptable 0,00

No pictures to display