



SEAT Alhambra: 1GD1415			
Vinnnumber:	<b>VSSZZZ7NZEVS11701</b>	Versionname:	<b>ALHAMBRA Ecom.Style DPF 136PK</b>
First Registrationdate:	<b>7/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>172987</b>	Power Kw:	<b>100</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4402</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>215/60/16/95 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

Assistance equipment	
Total cost ex VAT	3373,68
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------





Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84





Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 264,21



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84

