



VOLVO V60: 1HGZ876

| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber: | YV1FW31A1F1228038 | Versionname: | V60 BRE D3 Kinetic 136PK |
| First Registrationdate: | 18/07/2014 | Fiscalpower: | |
| Expertise Mileage: | 72233 | Power Kw: | 100 |
| Bodytype: | Break | Body color: | Dark Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2629 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|--------------------------|
| Radio CD | Central consol F | |
| Windows electric F | Luggage cover | |
| Windows electric R | Front parking sensors | |
| Cruise Control | Rear parking sensors | |
| Steering wheel multifunctional | Type of Tow bar | Tow bar removable |
| Seats F heated | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 215/55/16/97 H LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|



















| | |
|---|---------|
| Total cost ex VAT | 1010,23 |
| Wing R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Scratch(es), LI - Repair and paint (complete) | 318,35 |



| | |
|-----------------------------------|------|
| Wing F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|

| | | |
|---|---|--|
| <i>No pictures to display</i> | | 0,00 |
|  |  |  |
| Door R R, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | | 95,00 |
|  |  |  |
|  | | |
| Interior, Dirty, Cleaning | | 0,00 |
|  |  |  |
| Rear window, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | | 211,80 |
|  |  |  |
|  |  | |
| Bonnet, Chemical polution, LI - Repair and paint (complete) | | 290,08 |
|  |  |  |
| Bumper F L, Scratch(es), Acceptable | | 0,00 |
| <i>No pictures to display</i> | | |