


BMW SERIE 5 TOURING: 1ETE156

| | | | |
|-------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WBAMX11050DY13714 | Versionname: | 520dA |
| First Registrationdate: | 14/03/2013 | Fiscalpower: | |
| Expertise Mileage: | 129106 | Power Kw: | 120 |
| Bodytype: | | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2119 |
| Maintenance: | IN 16000 KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Seats electric F L |
| GPS storage | | Central consol F |
| GPS storage | HD | Luggage cover |
| Windows electric F | | Front parking sensors |
| Windows electric R | | Rear parking sensors |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 225/55/17/97 W LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 7 mm | Fr.R. | Michelin: 7 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 928,28 |
|-------------------|--------|

| | |
|--------------------------------------------------------------|-------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|





Door F R, Bad repair, P - Check 0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Stain, Acceptable 0,00



Tailgate, Dent(s), PDR - Knock out without painting 63,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Sill trim L, Scratch(es), It - Spot repair 115,56



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Door R L, Bad repair, P - Check 0,00



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Bad repair, P - Check 0,00



Wing F L, Dent(s) and scratch(es), It - Spot repair 115,56



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

