



BMW 1: 1FJC895

Vinnnumber:	WBA1C91020J513482	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	12/07/2013	Fiscalpower:	
Expertise Mileage:	96762	Power Kw:	85
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4201
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	150,00
-------------------	---------------

Roof pillar R, Repaired, P - Check	0,00
------------------------------------	-------------



Door R L, Dent(s), Acceptable	0,00
-------------------------------	-------------



Interior, Dirty, Cleaning	100,00
---------------------------	---------------



Bonnet, Scratch(es), Acceptable 0,00



Trunk lid covering R, Scratch(es), Acceptable 0,00



Wing R R, Scratch(es), Acceptable 0,00



Rear window, Not original part, Remove lettering 25,00



Bumper R, Scratch(es), Acceptable 0,00



Rear wiper blade, Damaged, E - Replace 25,00



Tailgate, Scratch(es), Acceptable 0,00



Windscreen, Repaired, Acceptable 0,00



Door R R, Dent(s), Acceptable 0,00



Roof, Dent(s), Acceptable 0,00

