



VOLVO V60: 1DNR383

Vinnnumber:	YV1FW84ABD1096876	Versionname:	V60 BRE DRiVe Kinetic St/St 115PK Aut.
First Registrationdate:	2/07/2012	Fiscalpower:	
Expertise Mileage:	149854	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4731
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage	HD	Seats electric F L
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/50/17/95 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2678,84
Door panel F L, Damaged, Acceptable			0,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Alloy rim F L, Scratch(es), Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Rear spoiler, Scratch(es), Acceptable 0,00



Tailgate, Scratch(es), 67 - Polish 0,00



Bonnet, Hail damage, PDR - Hail 275,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80





Bumper R, Scratch(es), 67 - Polish 0,00




Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Dent(s), Acceptable 0,00



Rear window, Scratch(es), E - Replace 370,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Covering mid pillar L, Hole, Repair/replace (lump sum) 110,64



Door R L, Dent(s), Acceptable 0,00

