



BMW 2 Active Tourer: 1HVZ975

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber: | WBA2C11090V335990 | Versionname: | 2 ACTIVE TOURER 218dA |
| First Registrationdate: | 1/01/2020 | Fiscalpower: | 150PK Aut. |
| Expertise Mileage: | 179840 | Power Kw: | 110 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2628 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | |
|------------------------------|------------------------------|
| Windows electric F | Sun Roof electric |
| Windows electric R | Panoramic roof |
| Cruise Control | Central consol F |
| Steering wheel multifunction | Luggage cover |
| Seats F heated | Front parking sensors |
| Radio multimedia | Rear parking sensors |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/60/16/92 H LightMetal | | | |
| Summer tyres: | Fr.L. | Continental: 3 mm | Fr.R. | Continental: 3 mm |
| | Re.L. | Continental: 3 mm | Re.R. | Continental: 3 mm |

Assistance equipment

| | |
|---|---------|
| Total cost ex VAT | 1652,40 |
| Ignition key, Missing, E - Replace | 150,00 |
| <i>No pictures to display</i> | |
| Front bumper, Damaged, Le - Replace and paint | 735,00 |



| | |
|---------------------------------------|------|
| Alloy rim R.P. Scratch(es) Acceptable | 0,00 |
|---------------------------------------|------|

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Damaged, E - Replace 0,00



Bumper grille F L, Damaged, E - Replace 32,40



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Foglight L, Missing, E - Replace 138,00



Registration Document, Missing, E - Replace 150,00

No pictures to display

Alloy rim F R, Damaged, E - Replace 235,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

