


LAND ROVER Evoque: 1EXM145

| | | | |
|-------------------------|--------------------------|--------------|----------------------------|
| Vinnnumber: | SALVB2DC3DH785081 | Versionname: | EVOQUE eD4 2WD Pure |
| First Registrationdate: | 15/04/2013 | Fiscalpower: | 150PK |
| Expertise Mileage: | 99496 | Power Kw: | 110 |
| Bodytype: | | Body color | Light Green |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Front | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Maintenance | OK | Parking lot | 4729 |
| Maintenance | GEEN MELDING | | |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 4 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |

Options

| | | | |
|--------------------------------|-------------------------------------|----------------------|-------------------|
| Radio CD | | Seats electric F L | |
| Windows electric F | | Seats electric F R | |
| Windows electric R | | Panoramic roof | |
| Cruise Control | | Central consol F | |
| Steering wheel multifunctional | | Luggage cover | |
| Radio multimedia | | Rear parking sensors | |
| Type of headlighting | Headlighting Halogen | Type of Tow bar | No Tow bar |
| Type of GPS | No GPS | | |
| Type of Lining | Lining leather and alcantara | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| 235/60/18/109 V LightMetal | | | | |
|----------------------------|-------|----------------------|-------|----------------------|
| Summer tyres: | Fr.L. | Pirelli: 7 mm | Fr.R. | Pirelli: 7 mm |
| | Re.L. | Pirelli: 8 mm | Re.R. | Pirelli: 7 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|--|--------|
| Total cost ex VAT | 552,02 |
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|


No pictures to display

| | |
|--|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete)

362,02



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

