



VOLVO XC60: 1EMJ355

Vinnumber:	YV1DZ31A1D2433023	Versionname:	XC60 D3 Kinetic Start/Stop 136PK
First Registrationdate:	22/01/2013	Fiscalpower:	
Expertise Mileage:	60992	Power Kw:	100
Bodytype:	SUV	Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2615
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Seats electric F L
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/60/18/107 V LightMetal			
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2636,50
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16





Door R R, Scratch(es), Acceptable 0,00

No pictures to display


Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 264,21



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Rearview mirror R complete, Broken, E - Replace 192,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical pollution, LI - Repair and paint (complete) 348,09

