


BMW 5 TOURING: 1KNF925

Vinnumber:	WBA5L11030D969444	Versionname:	2.0 518D (100KW) TOURING
First Registrationdate:	2/06/2015	Fiscalpower:	
Expertise Mileage:	90787	Power Kw:	100
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3118
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	708,00
-------------------	--------


Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---------------------------------------------------------	--------



Bonnet, Bad repair, Acceptable	0,00
--------------------------------	------




Sill outer R, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
-------------------------------------------------------------	--------



Wing F R, Bad repair, Acceptable	0,00
----------------------------------	------



Protection plate M, Deformed / Strained, E - Replace	84,00
------------------------------------------------------	-------

