



| FORD Fiesta: PR8791                |                          |              |                              |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber:                        | <b>WF0DXXGAKDDC60418</b> | Versionname: | <b>FIESTA BER Trend 75PK</b> |
| First Registrationdate:            | <b>27/09/2013</b>        | Fiscalpower: |                              |
| Expertise Mileage:                 | <b>129050</b>            | Power Kw:    | <b>55</b>                    |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Dark Blue</b>             |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>               |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>                 |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                    |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3719</b>                  |
| Number of doors:                   | <b>5</b>                 |              |                              |
| Number of seats:                   | <b>5</b>                 |              |                              |
| Number head rests:                 | <b>4</b>                 |              |                              |
| Rims summer:                       | <b>Steel</b>             |              |                              |
| Category:                          | <b>Passenger Car</b>     |              |                              |
| Oil level:                         | <b>OK</b>                |              |                              |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                              |

| Options                        |                               |
|--------------------------------|-------------------------------|
| Radio CD                       | Luggage cover                 |
| Windows electric F             |                               |
| Steering wheel multifunctional |                               |
| Radio multimedia               |                               |
| Type of headlighting:          | <b>Headlighting Halogen</b>   |
| Type of Lining:                | <b>Lining fabrics</b>         |
| Type of climate control:       | <b>Manual climate control</b> |

| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                    | <b>OK</b> | Transmission        | <b>OK</b>  |
|                              |           | Lighting            | <b>OK</b>  |
|                              |           | Wiperblades         | <b>OK</b>  |

| Degree of wear |                             |                          |       |                          |
|----------------|-----------------------------|--------------------------|-------|--------------------------|
|                | <b>195/50/16/88 T Steel</b> |                          |       |                          |
| Summer tyres:  | Fr.L.                       | <b>Bridgestone: 5 mm</b> | Fr.R. | <b>Bridgestone: 5 mm</b> |
|                | Re.L.                       | <b>Bridgestone: 6 mm</b> | Re.R. | <b>Bridgestone: 6 mm</b> |

| Assistance equipment                                    |         |
|---|---------|
| Total cost ex VAT                                       | 1652,16 |
| Wing F R, Scratch(es), Acceptable                       | 0,00    |
| <i>No pictures to display</i>                           |         |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 169,44  |



|   |        |
|---|--------|
| Wing R L, Scratch(es), LI - Repair and paint (complete) | 246,56 |
|---|--------|



Wheel cover F L, Scratch(es), E - Replace 24,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 24,00



Door F L, Scratch(es), LI - Repair and paint (complete) 254,68



Door R L, Scratch(es), LI - Repair and paint (complete) 254,68



Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Door F R, Scratch(es), LI - Repair and paint (complete) 254,68

