



OPEL Astra: 1FJG073

Vinnumber:	W0LPC6DA4D1130289	Versionname:	ASTRA BER ecoFLEX Essentia S&S 95PK
First Registrationdate:	15/07/2013	Fiscalpower:	
Expertise Mileage:	100561	Power Kw:	70
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3402
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1235,08
--------------------------	----------------


Wing R R, Dent(s) and scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)	481,50
--	---------------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
--	---------------



Door F L, Repaired, Acceptable	0,00
---------------------------------------	-------------




Wing R L, Bad repair, LI - Repair and paint (complete) 0,00



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Wing F L, Repaired, Acceptable 0,00



Door R L, Repaired, Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s), LI - Repair and paint (complete) 358,50



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 75,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display