


SKODA Octavia: 1HNC735

Vinnnumber:	TMBJG7NE4E0121196	Versionname:	OCTAVIA COMBI Ambition
First Registrationdate:	26/08/2014	Fiscalpower:	105PK
Expertise Mileage:	77705	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	12100	Parking lot:	4602
Maintenance:	OK		
Maintenance:	437 DAGEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS base	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	474,06
-------------------	--------

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Sill trim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

<i>No pictures to display</i>	Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Bumper cover R M, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Internal Boot Lining R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Front bumper, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	Door R L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Internal Boot Lining L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Roof pillar L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	Roof pillar R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Sill trim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Door F R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Windscreen, Repaired, Acceptable	0,00



	Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	Bumper R, Scratch(es), It - Spot repair	115,56



	Sill outer R, Dent(s), LI - Repair and paint (complete)	358,50
--	---	--------



	Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		