


BMW 3: 1HNT796

Vinnumber:	WBA3D91040J414698	Versionname:	3 BER 316d 116PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	180524	Power Kw:	85
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	19000 KM	Parking lot:	4614
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	HD
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control
Level control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Firestone: 3 mm	Fr.R.	Firestone: 3 mm
	Re.L.	Firestone: 4 mm	Re.R.	Firestone: 4 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	305,00
-------------------	--------







Door panel R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------



Door panel F L, Scratch(es), Acceptable	0,00
---	------

<i>No pictures to display</i>		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Rearview mirror R complete, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Boot carpet, Dirty, Cleaning		0,00
<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), 1 - Repair		100,00
		
Wing R L, Dent(s) and scratch(es), Acceptable		0,00
		
Bumper R, Not original part, Acceptable		0,00
		
Front bumper, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Seat cover F L, Tear, Acceptable		0,00
		
Wing R R, Not original part, Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), 1 - Repair		100,00
		
Door F L, Dent(s), Acceptable		0,00
		
Rocker panel inner F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Seat cover R L, Missing, E - Replace		5,00



Maintenance, Maintenance, Execute 0,00



Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), I - Repair 100,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display