



|                                    |                          |              |                                  |
|------------------------------------|--------------------------|--------------|----------------------------------|
| <b>VOLVO XC60: 1HNZ735</b>         |                          |              |                                  |
| Vinnnumber:                        | <b>YV1DZ87A4F2655780</b> | Versionname: | <b>XC60 D4 4WD Kinetic 163PK</b> |
| First Registrationdate:            | <b>2/09/2014</b>         | Fiscalpower: |                                  |
| Expertise Mileage:                 | <b>47176</b>             | Power Kw:    | <b>120</b>                       |
| Bodytype:                          | <b>SUV</b>               | Body color:  | <b>Red</b>                       |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                   |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                 |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2105</b>                      |
| Number of doors:                   | <b>5</b>                 |              |                                  |
| Number of seats:                   | <b>5</b>                 |              |                                  |
| Number head rests:                 | <b>5</b>                 |              |                                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                                  |
| Category:                          | <b>Passenger Car</b>     |              |                                  |
| Oil level:                         | <b>OK</b>                |              |                                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                  |

|                                |                              |                      |                   |
|--------------------------------|------------------------------|----------------------|-------------------|
| <b>Options</b>                 |                              |                      |                   |
| Radio CD                       |                              | Seats electric F L   |                   |
| Windows electric F             |                              | Central consol F     |                   |
| Windows electric R             |                              | Luggage cover        |                   |
| Cruise Control                 |                              | Rear parking sensors |                   |
| Steering wheel multifunctional |                              | Type of Tow bar      | <b>No Tow bar</b> |
| Radio multimedia               |                              |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                   |
| Type of climate control        | <b>Autom climate control</b> |                      |                   |

























|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                                   |                          |       |                          |
|-----------------------|-----------------------------------|--------------------------|-------|--------------------------|
| <b>Degree of wear</b> |                                   |                          |       |                          |
|                       | <b>235/65/17/104 V LightMetal</b> |                          |       |                          |
| Summer tyres:         | Fr.L.                             | <b>Continental: 5 mm</b> | Fr.R. | <b>Continental: 5 mm</b> |
|                       | Re.L.                             | <b>Continental: 6 mm</b> | Re.R. | <b>Continental: 6 mm</b> |

|                                      |            |            |                |
|--------------------------------------|------------|------------|----------------|
| <b>Assistance equipment</b>          |            |            |                |
| Repair kit                           | <b>Yes</b> | Compressor | <b>Yes</b>     |
| Total cost ex VAT                    |            |            | <b>4518,21</b> |
| Interior, Smell, Ozone treatment     |            |            | <b>152,58</b>  |
| <i>No pictures to display</i>        |            |            |                |
| Foglight L, Scratch(es), E - Replace |            |            | <b>156,00</b>  |



|   |               |
|---|---------------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | <b>254,16</b> |
|---|---------------|

|   |   |  |  |        |
|---|---|--|--|--------|
|     |     |     | Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) | 115,56 |
|    |    |    | Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)      | 382,02 |
|    |    |  | Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)        | 348,09 |
|    |    |    | Headlight L, Scratch(es), E - Replace                                    | 456,00 |
|   |   |  | Bumper moulding F L, Scratch(es), E - Replace                            | 17,28  |
|  |  |  | Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)      | 369,84 |
|  |  |  | Front bumper, Dent(s) and scratch(es), Le - Replace and paint            | 862,80 |
|  |  |  | Bumper moulding F, Broken, Le - Replace and paint                        | 120,00 |
|  |  |  | Maintenance book, Missing, E - Replace                                   | 0,00   |
| <i>No pictures to display</i>   |   |  |  |        |
|  |  |  | Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)      | 369,84 |



Interior, Dirty, Chemical cleaning 150,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door F R, Scratch(es), LI - Repair and paint (complete) 382,02

