



MERCEDES Vito: 1DUR300			
Vinnnumber:	WDF63960113759777	Versionname:	VITO 113 B/F SWB 136PK
First Registrationdate:	3/09/2012	Fiscalpower:	
Expertise Mileage:	126276	Power Kw:	100
Bodytype:	Transporter	Body color:	Red
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1106
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	No GPS	Type of Tow bar	No Tow bar
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	195/65/16/102 T Steel		
	Fr.L.	Fr.R.	Michelin: 5 mm
	Re.L.	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
		Jack	Yes


Total cost ex VAT	1963,47
Seat F L compl, Worn, Acceptable	0,00




Trunk door R R, Dent(s), LI - Repair and paint (complete)	238,76
---	--------



Bumper R, Dent(s), E - Replace	329,40
--------------------------------	--------




Door F R, Dent(s), LI - Repair and paint (complete) 286,76




Rearview mirror housing R, Scratch(es), E - Replace 50,00



Rearview mirror housing L, Scratch(es), E - Replace 50,00




Interior, Dirty, Acceptable 0,00



Bumper F, Broken, E - Replace 398,40



Windscreen, Broken, E - Replace 0,00



Steel rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display



Steel rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Steel rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 165,13



Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02





Roof, Bad repair, Paint	0,00
-------------------------	------



Trunk door R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F L, Repaired, Acceptable	0,00
--------------------------------	------



Wing R L, Dent(s), PDR - Knock out without painting	63,00
---	-------



Steel rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display