



## VOLKSWAGEN Touran: 1GGV360

Vinnnumber:	<b>WVGZZ1TZEW059686</b>	Versionname:	<b>TOURAN Highline BMT Start/Stop 105PK</b>
First Registrationdate:	<b>5/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>104679</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>19000</b>	Parking lot:	<b>4515</b>
Maintenance:	<b>189 DAGEN</b>		
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	<b>HD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar removable</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>598,80</b>
Wing R R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Dashboard, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Tailgate, Dent(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door F L, Scratch(es), 67 - Polish			<b>0,00</b>
<i>No pictures to display</i>			
Bumper F, Scratch(es), LI - Repair and paint (complete)			<b>211,80</b>



Wing R L, Scratch(es), 67 - Polish 0,00



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Internal Boot Lining R, Scratch(es), Acceptable 0,00

No pictures to display

Sunroof cover, Broken, Repair/replace (lump sum) 0,00



Door frame R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R L, Scratch(es), Acceptable 0,00

No pictures to display

Centre console, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display


Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Repaired, Acceptable 0,00



Backrest cover R R, Scratch(es), Acceptable 0,00

<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), E - Replace	80,20
	
Wing F L, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	