



VOLVO XC60: 1FGE808

Vinnumber:	YV1DZ31A1E2509073	Versionname:	XC60 D3 Kinetic 136PK
First Registrationdate:	20/06/2013	Fiscalpower:	
Expertise Mileage:	152754	Power Kw:	100
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2720
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	DVD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunction			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/108 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1899,04
-------------------	----------------

Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
---	---------------



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display


Bumper R, Deformed / Strained, LI - Repair and paint (complete) 302,16



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 430,02



Wing R L, Dent(s), LI - Repair and paint (complete) 369,84



Door R L, Dent(s), PDR - Knock out without painting 63,00



Rear window, Scratch(es), Acceptable 0,00



Bumper cover R M, Deformed / Strained, Le - Replace and paint 125,00



Door panel F R, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Repaired, No repair 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door panel F L, Tear, E - Replace

132,00

