



VOLVO V70: 1HNF100

Vinnumber:	YV1BW73CDF1318179	Versionname:	
First Registrationdate:	27/08/2014	Fiscalpower:	
Expertise Mileage:	135808	Power Kw:	133
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4619
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	531,80
-------------------	---------------

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display



Bumper F R, Scratch(es), Smart repair	110,64
---------------------------------------	---------------



Wing R L, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
----------------------------------------	-------------

<i>No pictures to display</i>		
Bonnet, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)		326,16
		
		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
