


BMW 3: 1GRR532

Vinnumber:	WBA3K110X0F830006	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	10/04/2014	Fiscalpower:	
Expertise Mileage:	150032	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 3800 KM	Parking lot:	2423
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	3898,35
-------------------	---------

Sill outer L, Scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Sill outer R, Scratch(es), LI - Repair and paint (complete) 310,50



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80





Interior, Dirty, Cleaning 25,00



Wing R R, Scratch(es), It - Spot repair 115,56



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 356,20



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Seat cover F L, Worn, P - Check 0,00



Step L, Scratch(es), Acceptable 0,00

Step L, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

