


BMW 3: 1JFP792

| | | | |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnnumber: | WBA3Y11040D451030 | Versionname: | 3 GRAN TURISMO 318d |
| First Registrationdate: | 4/12/2014 | Fiscalpower: | 143PK |
| Expertise Mileage: | 78099 | Power Kw: | 105 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3306 |
| Maintenance: | SERVICE IN 2200KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | HD | Luggage cover |
| GPS storage | | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/55/17/97 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 202,32 |
|-------------------|--------|

| | |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-------------------------------------|------|
| Bumper F, Stone chip(s), Acceptable | 0,00 |
|-------------------------------------|------|

No pictures to display

| | |
|--------------------------------|------|
| Wing F R, Repaired, Acceptable | 0,00 |
|--------------------------------|------|

No pictures to display

| | |
|-----------------------------------------|------|
| Door panel R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------------|------|

No pictures to display

| | |
|--------------------------------|------|
| Door R R, Repaired, Acceptable | 0,00 |
|--------------------------------|------|

No pictures to display

| | |
|---------------------------------|--------|
| Foglight R, Broken, E - Replace | 138,00 |
|---------------------------------|--------|



| | |
|-----------------------------------------------|-------|
| Backrest cover F L, Scratch(es), Smart repair | 64,32 |
|-----------------------------------------------|-------|



| | |
|--------------------------------|------|
| Door F R, Repaired, Acceptable | 0,00 |
|--------------------------------|------|

No pictures to display

| | |
|----------------------------------------|------|
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|

No pictures to display

| | |
|----------------------------------------|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|

No pictures to display

| | |
|----------------------------------------|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|

No pictures to display

| | |
|-------------------------------|------|
| Door R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|-------------------------------|------|
| Wing R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Tailgate, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display