


MERCEDES CLA: 1HSX083

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber: | WDD1173121N131978 | Versionname: | CLA BER 180 CDI 109PK |
| First Registrationdate: | 24/09/2014 | Fiscalpower: | |
| Expertise Mileage: | 144469 | Power Kw: | 80 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3233 |
| Maintenance: | SERV B3 IN 5500KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|-------------------------------|-----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Front parking sensors | |
| GPS storage | HD | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Windows electric R | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/91 H LightMetal | | | |
| Summer tyres: | Fr.L. | Yokohama: 6 mm | Fr.R. | Yokohama: 6 mm |
| | Re.L. | Yokohama: 5 mm | Re.R. | Yokohama: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 110,64 |
|-------------------|---------------|

| | |
|------------------------------------|---------------|
| Door panel R L, Hole, Smart repair | 110,64 |
|------------------------------------|---------------|



| | |
|--|-------------|
| Rearview mirror L complete, Missing, P - Check | 0,00 |
|--|-------------|



| | |
|-------------------------------------|------|
| Door frame R L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door frame R R, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |