


BMW 1: 1HGF133

Vinnnumber:	WBA1C91070P694091	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	14/07/2014	Fiscalpower:	
Expertise Mileage:	179312	Power Kw:	85
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3722
Maintenance:	-800KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1055,68
-------------------	----------------

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display


Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------



Wing R L, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Tailgate, Paint preparation, LI - Repair and paint (complete)	301,68
---	---------------



Wheel hub cap R R, Missing, E - Replace 10,00



Wheel hub cap F L, Missing, E - Replace 10,00



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Wheel hub cap R L, Missing, E - Replace 10,00



Bumper R, Deformed / Strained, Le - Replace and paint 651,00



Door F R, Dent(s), PDR - Knock out without painting 63,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel hub cap F R, Missing, E - Replace 10,00

