



LAND ROVER RANGE ROVER EVOQUE: FZ9296

Vinnnumber:	<b>SALVA2BN5HH176491</b>	Versionname:	<b>TD4 110kW SE 4WD Auto</b>
First Registrationdate:	<b>18/10/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>28240</b>	Power Kw:	<b>110</b>
Bodytype:	<b>SUV</b>	Body color	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3829</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear









Summer tyres:	225/65/17/106 V LightMetal			
	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1678,68</b>
Wing moulding F R, Scratch(es), E - Replace			<b>84,00</b>



Bonnet, Bad repair, Acceptable	<b>0,00</b>
--------------------------------	-------------

		Door F L, Scratch(es), LI - Repair and paint (complete)	382,02
		Wing trim R L, Scratch(es), E - Replace	96,00
		Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
		Door R R, Scratch(es), LI - Repair and paint (complete)	382,02
		Rearview mirror housing R, Scratch(es), Acceptable	0,00
No pictures to display			
		Door trim R R, Scratch(es), Smart repair	110,64
		Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84
		Ignition key, Missing, Acceptable	0,00
No pictures to display			