



|                                    |                          |              |                             |
|------------------------------------|--------------------------|--------------|-----------------------------|
| <b>BMW 5: 1HFL149</b>              |                          |              |                             |
| Vinnumber:                         | <b>WBA5J310X0D073644</b> | Versionname: | <b>5 TOURING 520d 163PK</b> |
| First Registrationdate:            | <b>8/07/2014</b>         | Fiscalpower: |                             |
| Expertise Mileage:                 | <b>85492</b>             | Power Kw:    | <b>120</b>                  |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Dark Blue</b>            |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>              |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                   |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3711</b>                 |
| Number of doors:                   | <b>5</b>                 |              |                             |
| Number of seats:                   | <b>5</b>                 |              |                             |
| Number head rests:                 | <b>5</b>                 |              |                             |
| Rims summer:                       | <b>Aluminium</b>         |              |                             |
| Category:                          | <b>Passenger Car</b>     |              |                             |
| Oil level:                         | <b>OK</b>                |              |                             |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                             |

|                                |                              |                       |                      |
|--------------------------------|------------------------------|-----------------------|----------------------|
| <b>Options</b>                 |                              |                       |                      |
| Radio CD                       |                              | Central consol F      |                      |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |                      |
| GPS storage                    |                              | Front parking sensors |                      |
| Windows electric F             |                              | Rear parking sensors  |                      |
| Windows electric R             |                              | Type of Tow bar       | <b>Tow bar fixed</b> |
| Cruise Control                 |                              |                       |                      |
| Steering wheel multifunctional |                              |                       |                      |
| Radio multimedia               |                              |                       |                      |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                      |
| Type of Lining                 | <b>Lining leather</b>        |                       |                      |
| Type of climate control        | <b>Autom climate control</b> |                       |                      |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                                  |                          |       |                          |
|-----------------------|----------------------------------|--------------------------|-------|--------------------------|
| <b>Degree of wear</b> |                                  |                          |       |                          |
|                       | <b>225/55/17/97 Y LightMetal</b> |                          |       |                          |
| Summer tyres:         | Fr.L.                            | <b>Michelin: 4 mm</b>    | Fr.R. | <b>Michelin: 4 mm</b>    |
|                       | Re.L.                            | <b>Bridgestone: 5 mm</b> | Re.R. | <b>Bridgestone: 5 mm</b> |

|  |            |            |                |
|--|------------|------------|----------------|
| <b>Assistance equipment</b>                                    |            |            |                |
| Repair kit   | <b>Yes</b> | Compressor | <b>Yes</b>     |
| <b>Total cost ex VAT</b>                                       |            |            | <b>1304,56</b> |
| <b>Bumper F, Scratch(es), LI - Repair and paint (complete)</b> |            |            | <b>254,16</b>  |



|   |               |
|---|---------------|
| <b>Alloy rim F R, Scratch(es), I - Repair</b> | <b>100,00</b> |
|---|---------------|



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete) 577,80



Sill outer R, Scratch(es), LI - Repair and paint (complete) 372,60

